


View of gate from afar



Close up of bent pipe



Left side of lock protector



Middle pipe to be repaired



Right Side of gate close up



Right Side



Rust around sign

Attachment 3: Pictures



Rust back of sign

Bottom portion of gate

